




Choose the Fast and simultaneous
Multi Frequency programs or between
49 single frequencies from 4 to 45 kHz.

45 kHz
35 kHz
28 kHz
21 kHz
15 kHz
7 kHz
4 kHz



The above graphic illustrates the sensitivity and the iron discrimination capability depending on frequency and the advantage of Fast Multi Frequency programs covering a large spectrum of targets. This is only a basic schematic which can vary depending the programs and real terrain conditions.

